Examples of Construction/Demolition Debris that are Hazardous Waste <u>DO NOT PLACE IN DUMPSTER.</u>

Lead – Paint chips, Pipe, Sheets, Lead-Acid Batteries (Automotive or Sealed in emergency lights)

Mercury – Lamps, Thermostats, Thermometers

Corrosives/Caustics – Cleaners, Muriatic Acid, Peel-Away Stripper, Rechargeable Batteries (NiCd, Lead, Mercury, Lithium, Li-ion), Solder Flux, Concrete Curing Compounds

Flammables - Oil Based Paints, Mineral Spirits, Solvents, Gasoline, Epoxy Coatings, Torch Gasses,

Rags – used with the following Solvents if the rag will not be reused (even if rag appears dry):
methylene chloride, trichloroethylene (TCE), chlorobenzene, toluene, methyl ethyl ketone (MEK),
isobutanol, benzene, etc. Examples could come from brake cleaners, adhesive removers,

Aerosol Containers – ALL (Full, Half-Full, Empty; Paint, Compressed Air, Spray Foam, Raid, Lysol, etc.)

Gas Cylinders – Small, single use bottles (Propane, MAPP, Butane, Oxygen)

Methyl Ethyl Ketone – PVC Pipe Solvent

Silver / Lead – Pipe Solder, Lead piping, traps, or sheets

Oxidizers – Chlorine (Cleaners/Bleaches), Nitrates, Peroxides (Carpet Stain Removers), Permanganates, Dichromates, Epoxy Hardeners,

Pesticides – Any pesticide, herbicide, fungicide, rodenticide, insecticide, or other similar product.

Other Wastes

Smoke Detectors: Radioactive

Asbestos: Bagged, Chain of Custody, Manifested to Approved Landfill

Any Liquids: Only down drain if POTW (MUB for Morgantown) has given Written Approval

Polychlorinated Biphenyls (PCBs): Managed per TSCA, WVU Disposes thru Hazardous Waste Vendor Solid Construction Debris: Must be Permitted landfill, Provide Weight Tickets to WVU Project Manager Extra Materials (Paint, Cleaners, Chemicals): Cannot go to Landfill, Only Leave on Site if Requested by WVU

Project Manager

For Any Spills/Questions/Concerns, Contact WVU EH&S at 304-293-3792